

REMARKS


Amendments to the Drawings

As originally filed, Figure 1 failed to identify all of the structures exposed in the sectional portion. Lead lines and reference numbers have been included to identify the following structures: upper acquisition layer 52, lower acquisition layer 54, core wrap top layer 56, and storage layer 60. A marked-up drawing showing the additions in red has been provided for the Examiner's convenience.

Support for these additions may be found in the specification on page 7, line 1 to 17. Further support for these additions may be found in Figure 2 wherein the structures of the upper acquisition layer 52, the lower acquisition layer 54, the core wrap top layer 56, and the storage layer 60 have been identified.

It is respectfully requested that these changes be accepted and that the replacement drawing sheet 1/5 incorporating the changes be entered.

Respectfully submitted,

By: 

Eric T. Addington
Registration No. 52,403
Phone: (513) 626-1602
Fax: (513) 645-2954

August 10, 2004

Customer No. 27752

